PRINTED: 11/02/2011 FORM APPROVED

STATEMENT OF DEFICIENCIES NO PLAN OF CORRECTION (X1) PROVIDENSUPPLIES IDENTIFICATION NUM TN1001		UMBER:	(X2) MULTIPLE CONSTRUCTION A. BUILDING 01 - MAIN BUILDING 01 B. WING:		(X3) DATE SURVEY GOMPLETED 10/31/2011		
1633 HIL			DRESS, CITY, STATE, ZIP CODE LVIEW DRIVE THTON, TN 37643				
(X4) ID PREFIX TAG	SUMMARY STATEMENT OF DEFICIENCIES (EACH DEFICIENCY MUST BE PRECEDED BY FULL REGULATORY OR LSC IDENTIFYING INFORMATION)			ID PREFIX TAG	PROVIDER'S PLAN OF CORRECTION (EACH CORRECTIVE ACTION SHOULD BE CROSS-REFERENCED TO THE APPROPRIATE DEFICIENCY)		(X5) COMPLETE DATE
N 002	G REGULATORY OR LSC IDENTIFYING INFOR		rvey ensure	N 002	2. Environmental Supervisor ensured on 10/31/11 that all oxygen concentrators and bed/air pumps (medical devices) were directly plugged to the wall receptacle. 3. Environmental Supervisor was inserviced on 11/8/11 regarding state and federal requirements on the use of extension cords and multiple outlet adapters. 4. The weekly maintenance schedule has been revised to include all medical devices to ensure Oxygen Concentrators and bed/air pumps are directly plugged into wall receptacles. Environmental Supervisor will report results to the Quality Assurance Performance Improvement Committee. The Quality Assurance Performance Improvement Committee will review maintenance logs for 3 months and/or until 100% in compliance. The Quality Assurance Performance Improvement Committee is comprised of the Medical Director, Administrator, Director of Nursing, Assistant Director of Nursing, Resident Assessment Nurses, Social Services, Activities Director, Dietary Manager, Environmental Supervisor and Rehab Manager.		
		20			10 20 20	*	(#U)
	* a		t				.6